

ERROR MEMORY REPORT

Date: 02/13/16 21:23:55
ECU: IHKA39_2
JobStatus: OKAY
Variant: IHKA39_2

RESULT: 6 errors in error memory !

0 Ventilation flap motor

Error frequency : 10

Open circuit
Error present

Errorcode: 00 44 0A 3C 3C 00 8D 08 10 03 7C

1 Air circulation flap motor

Error frequency : 10

Open circuit
Error present

Errorcode: 01 44 0A 3C 3C 00 8D 08 10 03 7C

2 Footwell flap motor

Error frequency : 10

Open circuit
Error present

Errorcode: 02 44 0A 3C 3C 00 8D 08 10 03 7C

3 Defroster flap motor

Error frequency : 10

Open circuit
Error present

Errorcode: 03 44 0A 3C 3C 00 8D 08 10 03 7C

4 Rear compartment flap motor

Error frequency : 10

Open circuit
Error present

Errorcode: 04 44 0A 3C 3C 00 8D 08 10 03 7C

8 Heat exchanger sensor right

Error frequency : 10

Short circuit to batt+
Error present

Errorcode: 08 41 0A 3C 3C 00 8D 08 10 03 7C

=====