

ERROR MEMORY REPORT

Date: 06/03/16 15:13:23
ECU: DSC57
JobStatus: OKAY
Variant: DSC57

RESULT: 1 errors in error memory !

114 pressure Sensor (Offset)

Error frequency : 255

Vehicle speed 24.56 km/h

ASC not passiv
ABS-control passiv
stop light switch off
ASC-control passiv
ACB passive
HBA passive
ECD passive
HDC passive

=====