

E R R O R   M E M O R Y   R E P O R T

Date: 12/30/12 12:55:42  
ECU: MS430DS0  
JobStatus: OKAY  
Variant: MS430DS0

RESULT: 2 errors in error memory !

191 Lambda probe heating downstream sensor 2

Error frequency : 11  
Logistic counter: 40

N_32	1312.00	rpm
MAF	59.92	mg/stk
V_LS_DOWN_2	0.48	V
R_MV_LS_DIAG_DOWN_2	4626.00	Ohm
aufgetreten vor (rel. BZ)	44.30	h

---  
---  
---

Cat-sensor heater defective  
Error to relevant  
Error debounce  
Error currently available  
sporadic Error

Errorcode: BF F8 0B 28 29 0B 5F 12 68 1D

242 burning fail Cylinder 5

Error frequency : 1  
Logistic counter: 10

TCO	15.75	Grad C
N_32_TOL	1472.00	rpm
MAF_TOL	212.44	mg/stk
MAF_BOL	163.41	mg/stk
aufgetreten vor (rel. BZ)	14.20	h

---  
---  
---

Misfire CARB\_B1  
Error to relevant  
Error debounce  
Error currently not available  
sporadic Error

Errorcode: F2 B2 01 0A 55 2E 27 1E 69 4A